

A 225 AC/DC - A 250 AC/DC

OWNER'S MANUAL

KEEP THIS MANUAL



The technical specifications and the wiring diagrams contained in this owner's manual are valid only for the model that has the part number indicated below.

A 225 AC/DC: ALW-M110500425

A 250 AC/DC: ALW-M110500426



Air Liquide Welding is a trademark of L'Air Liquide S.A.

TABLE OF CONTENTS

1 SAFETY PRECAUTIONS - READ BEFORE USING

1.1	INSTALLATION OF EQUIPMENT	3
1.2	PERSONAL PROTECTION	3
1.3	FIRE AND EXPLOSION PREVENTION	4
1.4	METAL FUME HAZARDS	4
1.5	TRANSPORTING THE POWER SOURCE	5
1.6	MAGNETIC FIELDS CAN AFFECT PACEMAKERS	5
1.7	H.F. RADIATION CAN CAUSE INJURY	5
1.8	ARC WELDING CAN CAUSE INTERFERENCE	5
1.9	WELDING AND THE EFFECTS OF LOW FREQUENCY AND MAGNETIC FIELDS	5
1.10	PRINCIPAL SAFETY STANDARDS	6

2 SPECIFICATIONS AND DESCRIPTION

2.1	DESCRIPTION	7
2.2	SPECIFICATIONS	7
2.3	COMES COMPLETE WITH	7
2.4	DUTY CYCLE AND OVERHEATING	8
2.5	VOLT-AMPERE CURVES	9

3 OPERATION

3.1	FRONT PANEL CONTROLS	10
-----	----------------------	----

4 INSTALLATION

4.1	CONNECTING THE EQUIPMENT TO THE MAIN SUPPLY	11
4.2	SELECTING A LOCATION	11
4.3	CONNECTION AND PREPARATION OF EQUIPMENT FOR STICK-ELECTRODE WELDING	11
4.4	WELDING PARAMETERS	12
4.5	INTERNAL CONNECTION FOR OPERATING 230, 460 OR 575 VOLTS	13
4.6	HOW TO INSTALL THE WHEELS	13

5 MAINTENANCE AND TROUBLESHOOTING

5.1	ROUTINE MAINTENANCE	14
5.2	TROUBLESHOOTING	14

6 A 225 AC/DC ELECTRICAL DIAGRAM

7 A 250 AC/DC ELECTRICAL DIAGRAM

8 A 225 AC/DC SPARE PARTS LIST

9 A 250 AC/DC SPARE PARTS LIST



WARNING

Read and understand this entire Owner's Manual before installing, operating or servicing this equipment. While the information contained in this Owner's manual represents our best judgment, Air Liquide assumes no liability for its use.

Reproduction of this work, in whole or part, without written permission of the publisher is prohibited.

All rights reserved.

The publisher does not assume and hereby disclaims any liability to any party for any loss or damage caused by any error or omission in the Air Liquide A 225 AC/DC – A 250 AC/DC Owner's Manual, whether such error results from negligence, accident or any other causes.

1. SAFETY PRECAUTIONS - READ BEFORE USING



The use of welding equipment can cause injury to the operator. The reading and understanding of the safety standards mentioned below is compulsory prior to connecting, preparing, using or transporting welding equipment.

1.1 INSTALLATION OF EQUIPMENT

1. Installation and maintenance of equipment must be performed in compliance with local safety standards.



2. Frequently inspect the welder plug, receptacle and wiring. If damaged, replace immediately with approved electrical connections and adequately sized wiring.
3. Connect the welding ground as near as possible to the operating area.
4. Do not pass welding equipment cables through or near lifting chains, crane cables or any electrical lines.
5. If earth grounding of the workpiece is required, ground it directly with a separate cable.
6. Do not touch the electrode if you are in contact with the work, ground or another electrode from a different welding machine.
7. Use only well-maintained equipment. Repair or replace damaged parts immediately. Maintain welding equipment according to owner's manual.
8. Never use welding equipment near water. Do not spray water or other liquids on the welding equipment.

9. Avoid direct contact between wet garments and metal parts that are electrically charged.
10. Always wear gloves and rubber-soled shoes when working in wet areas or standing on metal surfaces.
11. Always turn off welding equipment that is not being used. Do not leave welding equipment unattended.

Significant DC voltage exists after the removal of input power to inverters. Always discharge input capacitors before touching any parts. Service work should be completed by qualified personnel only.

1.2 PERSONAL PROTECTION

1. Welding operations produce radiation, noise, heat and noxious fumes. Suitable safety precautions must be taken to minimize the risk.



2. Wear fire resistant work gloves, long sleeve shirts, pants, safety shoes, cap and welding helmet to protect the skin from radiation and metal sparks.



3. Always wear ear protection.
4. Always wear eye protection with side shields.
5. Position a fire resistant screen around the welding area to protect bystanders from radiation, sparks and slag.



6. Compressed gas cylinders are potentially dangerous. Consult the supplier for correct handling procedures. Always protect compressed gas cylinders from the sun's rays, flames and sudden temperature changes.

1.3 FIRE AND EXPLOSION PREVENTION



Hot slag and sparks can cause fire. The risk of fire and explosion can be minimized by removing all flammable material from the welding area.

1. Always perform welding operation with caution. Containers and tubes that have been emptied and thoroughly cleaned still represent a potential hazard.
2. Never perform welding operations or cut a closed container or pipe.
3. Never perform welding operations on open containers or pipes that may have been contaminated with substances that could explode or react when exposed to heat or humidity.
4. As a preventative measure, keep fire extinguishers near the welding operation.

1.4 METAL FUME HAZARDS



Welding fumes and gases may be hazardous if inhaled.

1. Install a ventilation system in the welding area.
2. Use a forced air system when welding lead, beryllium, cadmium, zinc, zinc-coated or painted material. Always wear a protective mask.
3. If the ventilation system is inadequate, use an air respirator.
4. Beware of gas leaks. Shielding gases such as argon are heavier than air and when used in small spaces, will replace the air.

5. In the event that a welding operation occurs in a confined place, the operator should be accompanied by another person.
6. Always keep gas cylinders in a well-ventilated area. Close the main gas valve when cylinder is not in use.
7. Do not perform welding operations near chlorinated hydrocarbon vapors produced by degreasing or painting. The heat generated by arc rays can react to form phosgene, a highly toxic gas.
8. Irritation of the eyes, nose and throat are symptoms of inadequate ventilation. Take immediate steps to improve ventilation. Do not continue welding if symptoms persist.

1.5 TRANSPORTING THE POWER SOURCE

1. The welding machine may be carried by the handle.
2. Always disconnect the power source and accessories from the main supply before lifting or handling the welding equipment.
3. Do not drag, pull or lift welding equipment by the weld cables.

1.6 MAGNETIC FIELDS CAN AFFECT PACEMAKERS



1. Keep pacemaker wearers away from welding operations.
2. Pacemaker wearers should consult with a physician prior to being exposed to any welding or cutting operation.

1.7 H.F. RADIATION CAN CAUSE INJURY



1. High frequency (HF) emissions can interfere with radio navigation, safety devices, computers and communication equipment.
2. Installation of welding equipment should be performed by a qualified electrician.
3. The operator is responsible for having a qualified electrician correct any interference problem resulting from the welding equipment installation.
4. If notified by the FCC about interference, stop using the welding equipment immediately.
5. Have the welding equipment installation checked and maintained on a regular basis.
6. Keep high-frequency source doors and panels tightly shut. Keep spark gaps at the correct setting and use grounding to minimize the possibility of interference.

1.8 ARC WELDING CAN CAUSE INTERFERENCE



1. Electromagnetic energy can interfere with sensitive electronic equipment such as computers and computer-driven equipment like robots.
2. Be sure that all equipment in the welding area is electro-magnetically compatible.
3. To reduce possible interference, keep weld cables as short as possible, close together and down low.
4. Locate welding operations at least 100 meters (350 feet) away from any sensitive electronic equipment.
5. Be sure welding equipment is installed and grounded according to this manual.
6. If interference still occurs, the operator must take extra measures such as moving the welding machine, using shielded cables, using line filters, or shielding the work area.

1.9 WELDING AND THE EFFECTS OF LOW FREQUENCY AND MAGNETIC FIELDS

As welding current flows through welding cables, it can cause electromagnetic fields. To reduce magnetic fields, use the following procedures:

1. Keep cables close together by twisting or taping them.
2. Arrange cables to one side and away from the operator.
3. Do not coil or drape coils around operators body.
4. Keep welding power source and cables as far away from the operator as practically possible.
5. Connect work clamp to workpiece as close to the weld as possible.

1.10 PRINCIPAL SAFETY STANDARDS

Safety in Welding and Cutting, ANSI Standard Z49.1 from the American Welding Society, 550 N.W. Lejeune Rd., Miami, FL 33126.

Safety and Health Standards, OSHA 29 CFR 1910, from the Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402.

Recommended Safe Practices for the Preparation for Welding and Cutting of Containers That Have Held Hazardous Substances, American Welding Society Standard AWS F4.1, from the American Welding Society, 550 N.W. Lejeune Rd., Miami, FL 33126.

National Electrical Code, NFPA Standard 70, from the National Fire Protection Association, Batterymarch Park, Quincy, MA 02269.

Safe Handling of Compressed Gases in Cylinders, CGA Pamphlet P-1, from the Compressed Gas Association, 1235 Jefferson Davis Highway, Suite 501, Arlington, VA 22202.

Code for Safety in Welding and Cutting, CSA Standard W117.2, from the Canadian Standards Association, Standard Sales, 178 Rexdale Boulevard, Rexdale, Ontario M9W 1R3.

Safe Practices For Occupation And Educational Eye And Face Protection, ANSI Standards Z87.1 from the American National Standards Institute, 1430 Broadway, New York, NY 10018.


Cutting And Welding Processes, NFPA Standards 51B, from the National Fire Protection Association, Batterymarch Park, Quincy, MA 02269.

EQUIPMENT INSTALLATION AND MAINTENANCE MUST BE PERFORMED IN COMPLIANCE WITH LOCAL SAFETY STANDARDS.




Electric shock could be fatal

1. Never touch exposed electrical parts.
2. Switch off and disconnect the power source before installing or opening.
3. Installation may be performed by qualified persons only.
4. Installation procedure must comply with national electricity standards and all other relevant regulations.



Fumes and gases may represent a safety hazard. Fumes and gases generated during welding may be dangerous if inhaled over a long period of time.

1. Keep clear of fumes.
2. Ventilate welding area or wear a breathing mask.
3. Install a natural or forced air ventilation system in the work area.




Use a protective mask with suitable glass filter (at least NR10) to safeguard eyes.

1. Wear appropriate eye, ear and body protection equipment.
2. Protect face, ears and neck during welding operations. Advise other persons in the vicinity to look away and stand clear of arc rays and hot metal.



Moving parts may cause injury.

1. Keep clear of hazardous areas, such as moving rollers.
2. Keep all doors, panels and covers closed and in place.



Hot areas may cause injury.

Let the power source or other parts cool before performing any maintenance or servicing.



Welding wire may cause injury.

Do not point the torch toward any part of the body, other persons or any type of metal when unwinding welding wire.



WELDING MAY CAUSE FIRES OR EXPLOSIONS. Never weld near inflammable materials.

1. Beware of weld flame. Always keep a fire extinguisher close at hand.
2. Never place welding equipment on inflammable surfaces.
3. Do not weld in closed containers.
4. Let welding equipment and material cool before handling them.



A falling power source or other equipment may cause serious injury to persons or damage to objects.

1. Always make use of the handle to lift power source (applies to portable models).
2. Use eye bolts and adequate lifting equipment to raise the power source.



The positioning of welding equipment on inflammable surfaces could lead to fire outbreak or explosion.

1. Never position equipment on combustible or inflammable surfaces.
2. Do not install equipment in the vicinity of inflammable liquids.

• **INSTALLATION AND MAINTENANCE OPERATIONS MUST BE PERFORMED BY QUALIFIED PERSONS ONLY.**

• **BEFORE INSTALLING** the power source, check that the power socket satisfies ampere and voltage requirements (see data table plate). **ENSURE** that the socket is protected by appropriate fuses and automatic switches.

• **CONNECT** an approved standard plug corresponding to the system socket to the power supply cable.

2. SPECIFICATIONS AND DESCRIPTION

2.1 DESCRIPTION

The **225 AC/DC** sets a new standard for economical AC/DC arc welding machines. This ruggedly-built welder is a proven performer with serious amperage to burn 2.5 mm ($\frac{3}{32}$ in) to 4.0 mm ($\frac{5}{32}$ in) low-hydrogen and special-alloy electrodes. A standard running gear improves mobility and assists the operator in positioning the equipment for those hard-to-reach areas. Standard dinse connections increase the versatility of the equipment and make welding cable replacement an easy task.

The 230/460 volt, 1-phase input power gives operators the option of choosing the power connections that are right for them. Infinite current regulation allows precise setting of amperage to achieve the exact heat for your welding needs.

The **250 AC/DC** sets a new standard for AC/DC arc welding machines. This ruggedly-built welder is a proven performer with serious amperage to burn 2.5 mm ($\frac{3}{32}$ in) to 4.0 mm ($\frac{5}{32}$ in) low-hydrogen and special-alloy electrodes. A standard running gear improves mobility and assists the operator in positioning the equipment for those hard-to-reach areas. Standard dinse connections increase the versatility of the equipment and make welding cable replacement an easy task.

The 230/460/575 volt, 1-phase input power gives operators the option of choosing the power connections that are right for them. Infinite current regulation allows precise setting of amperage to achieve the exact heat for your welding needs.

2.2 SPECIFICATIONS

A 225 AC/DC

Welding Amp Range		25 - 150 Amps (DC Output) 40 - 225 Amps (AC Output)		
Rated AC Input	Volts	Phase	Hertz	Amps
	230	1	60	50
	460	1	60	25
Rated DC Output		Amps	Duty Cycle	Volts
Max OCV 79V		150A	20%	26V
Rated AC Output		Amps	Duty Cycle	Volts
Max OCV 60V		225A	20%	25V

A 250 AC/DC

Welding Amp Range		25 - 180 Amps (DC Output) 40 - 250 Amps (AC Output)		
Rated AC Input	Volts	Phase	Hertz	Amps
	230	1	60	70
	460	1	60	35
	575	1	60	28
Rated DC Output		Amps	Duty Cycle	Volts
Max OCV 79V		180A	30%	27V
Rated AC Output		Amps	Duty Cycle	Volts
Max OCV 70V		250A	30%	30V

2.3 COMES COMPLETE WITH:

A 225 AC/DC

1. 2.4 m (8 ft) input power cord without plug
2. Handle and running gear



A 250 AC/DC

1. Handle and running gear



For options and accessories contact your distributor.



2.4 DUTY CYCLE AND OVERHEATING:



Duty cycle is the percentage of 10 minutes that the unit can weld at its rated output without overheating. If the unit overheats, the weld output will stop.

To correct this situation, wait fifteen minutes for the unit to cool. Reduce amperage or duty cycle before starting to weld again.





2.5 VOLT-AMPERE CURVES

Volt-ampere curves show the maximum voltage and amperage output capabilities of the welding power source. Curves of other settings fall under curves shown.



3. OPERATION

3.1 FRONT PANEL CONTROLS



1. AMPERAGE ADJUSTMENT CONTROL
2. POWER-ON LIGHT
3. POWER SWITCH
4. AMPERAGE INDICATOR

- 5/6. AC WELD OUTPUT RECEPTACLE
7. POSITIVE WELD OUTPUT RECEPTACLE
8. NEGATIVE WELD OUTPUT RECEPTACLE
9. DATA PLATE

4. INSTALLATION



Before connecting, preparing or using equipment, read Section 1: Safety Precautions.

4.1 CONNECTING THE EQUIPMENT TO THE MAIN SUPPLY

The equipment is shipped without an installed plug.

For the A 225 AC/DC, use a plug that is suitable for carrying the amps indicated on the data plate.

For the A 250 AC/DC, install a #8 or larger input power cord to the internal connections indicated in section 4.5. Use a plug that is suitable for carrying the amps indicated on the data plate.

Check to ensure that the power outlet is equipped with a fuse that is capable of carrying the amps indicated on the data plate of this unit.

4.2 SELECTING A LOCATION



Special installation may be required where gasoline or volatile liquids are present (See NEC Article 511 or CEC Section 20). Do not move or operate this equipment where it could tip over. When selecting a location for this equipment, ensure that the following guidelines are followed.

1. Use data plate to determine input power requirements.
2. The operator must have unobstructed access to all controls and equipment connections.
3. Do not position equipment in small, closed places. Ventilation of the power source is extremely important. Make sure that the louvers on the side panels are not obstructed and that there is no risk of obstruction during operation.

4. Avoid areas where dust or other objects could be sucked into the system.
5. Equipment must not obstruct corridors or work activities of other personnel.
7. Position the power source securely to avoid falling or overturning.
8. Understand the risk of falling equipment situated in overhead positions.

4.3 CONNECTION AND PREPARATION OF EQUIPMENT FOR STICK-ELECTRODE WELDING.

Connect all welding accessories carefully to prevent power loss. Carefully follow safety precautions described in section 1.

TURN OFF WELDER BEFORE MAKING CONNECTIONS.

DC MODE

1. Connect the ground cable to the negative receptacle and locate the ground clamp near the welding zone.
2. Connect the electrode cable to the positive receptacle and fit the selected welding electrode into the electrode holder.
3. Use the above connection for welding electrodes that use DCEP (Reverse Polarity) welding current. Reverse the connection for welding electrodes that use DCEN (Straight Polarity) welding current.

AC MODE

1. Connect the ground cable and the electrode cable to the AC receptacles.
2. Fit the selected welding electrode into the electrode holder.

4.4 WELDING PARAMETERS

Electrode Amperage and Polarity Chart							
Electrode	Size (MM)	Size (IN)	Optimum Amperage	AC	DC	Position	Penetration
LA 6010	2.5	$\frac{3}{32}$	75	No	EP	All	Deep
	3.2	$\frac{1}{8}$	115				
Ultra 11	2.5	$\frac{3}{32}$	70	YES	EP	All	Deep
	3.2	$\frac{1}{8}$	115				
LA 6013	2.5	$\frac{3}{32}$	70	YES	EP, EN	All	Low
	3.2	$\frac{1}{8}$	115				
LA 7014	2.5	$\frac{3}{32}$	80	YES	EP, EN	All	Medium
	3.2	$\frac{1}{8}$	130				
Exelarc 18	2.5	$\frac{3}{32}$	90	YES	EP	All	Low
	3.2	$\frac{1}{8}$	120				
LA 7018	2.5	$\frac{3}{32}$	90	YES	EP	All	Low
	3.2	$\frac{1}{8}$	130				
LA 7024	2.5	$\frac{3}{32}$	105	YES	EP	Flat and Horizontal	Low
	3.2	$\frac{1}{8}$	140				
EP = Electrode Positive (Reverse Polarity) EN = Electrode Negative (Straight Polarity)							

4.5 INTERNAL CONNECTION FOR INSTALLING 230, 460 OR 575 VOLTS




TURN OFF WELDER BEFORE MAKING CONNECTIONS.


A 225 AC/DC



A 250 AC/DC



4.6 HOW TO INSTALL THE WHEELS



5. MAINTENANCE AND TROUBLESHOOTING



Disconnect power before maintenance.
Service more often during severe conditions.



5.1 ROUTINE MAINTENANCE

Every three (3) months, perform the operations below:

1. Replace unreadable labels
2. Clean and tighten weld terminal connections
3. Repair or replace worn hoses and cables
4. With dry compressed air, blow out the unit to reduce the build-up of dust.

Every six (6) months perform the operations below:

Blow out the inside of the unit


Increase frequency of cleaning when operating in dirty or dusty conditions.

5.2 TROUBLESHOOTING

PROBLEM	SOLUTION
No weld output; fan runs.	Be sure line disconnect switch is in "ON" position.
	Check and replace line fuses if open. Reset breakers if necessary.
Fan does not run; weld output okay.	Be sure nothing is blocking movement of fan. If fan does not run freely, replace fan motor.
Erratic weld current.	Clean and tighten all weld cable connections.
Erratic arc with excessive spatter.	Use dry, properly-stored electrodes.
	Shorten arc length.
	Reduce amperage setting.
Electrode freezing to work.	Increase amperage setting.
	Increase arc length.
	Use dry, properly-stored electrodes.
Noise and vibration from shunt block.	Lubricate shunt block and/or tighten adjustment screws.


6. A 225 AC/DC ELECTRICAL DIAGRAM

A 225 AC/DC




7. A 250 AC/DC ELECTRICAL DIAGRAM

A 250 AC/DC



8. A 225 AC/DC SPARE PARTS LIST




A 225 AC/DC

A 225 AC/DC

R.	CODE	DESCRIPTION
02	ALW-SP800000726	RECTIFIER
08	ALW-SP800044683	INPUT CORD
09	ALW-SP038088156	STRAIN RELIEF
12	ALW-SP2EINN0500F	OUTPUT WELDING RECEPTACLE
14	ALW-SP073010181	FAN UNIT
23	ALW-SP035034011	POWER ON SWITCH
24	ALW-SP800051001	TRANSFORMER
24.1	ALW-SP800019451	SHUNT
26	ALW-SP2VVEN250P.1	FAN
27	ALW-SP2ESEG10001	LED
29	ALW-SP090005110	FIXED WHEEL
60	ALW-SP090015303	SPEED HANDLE
66	ALW-SP800050463	ADJUSTING SCREW
69	ALW-SP800050893	STABILIZER
77	ALW-SP800042199	POINTER

9. A 250 AC/DC SPARE PARTS LIST



A 250 AC/DC

R.	CODE	DESCRIPTION
02	ALW-SP800019131	RECTIFIER
09	ALW-SP038088155	STRAIN RELIEF
12	ALW-SP2EINN0500F	OUTPUT WELDING RECEPTACLE
14	ALW-SP073010180	FAN UNIT
23	ALW-SP035036011	POWER ON SWITCH
24	ALW-SP800050891	TRANSFORMER
24.1	ALW-SP800019450	SHUNT
26	ALW-SP2VVEN250P0	FAN
27	ALW-SP2ESEG10001	LED
29	ALW-SP090005150	FIXED WHEEL
60	ALW-SP090015304	SPEED HANDLE
66	ALW-SP800050463	ADJUSTING SCREW
69	ALW-SP800050893	STABILIZER
77	ALW-SP800042030	POINTER